```
echidna SPEC :: plot_transform
```

1. Plots rotational-transform profile or safety-factor (q-profile).

2. This routine is activated by clicking on the `pressure/transform` window, see `plot_prestran_event` for details.

3. The postscript file, if created, is given the name `ext.iota.ps`.

4. The "smooth" polynomial profile, as defined by the polynomial in `amaiactable`, is constructed.

`plot_transform.pro`

last modified on 2012-06-04 ;